



FIG. 1






LAYER 2


= SMT CUTOUT AREAS AREAS


FTH COMPONENT CUTOUT

* PTH LEAD CUTOUT AREAS

F16. 3












FIGURE 1